

Top 5 Suspension Problems That Shops and DIYers Commonly Misdiagnose

SUSPENSIA.COM

Struts, racks, and alignments get blamed for a lot of problems they didn't cause. In many cases the real cause is a worn chassis part: a sway bar link, a ball joint, a tie rod end, a control arm bushing, or a strut mount. Here are five common misdiagnoses, and how to find the part that's actually worn.

01 Tire Wear Blamed On Alignment When the Alignment Is In Spec

Worn struts usually make a vehicle bouncy or floaty. They rarely clunk. One of the most common sources is a sway bar end link or sway bar bushing, which is a much cheaper part. Worn strut mounts, ball joints, and control arm bushings are also common culprits. A loose exhaust hanger or heat shield can sound like any of them. To find it, grab each end link and try to twist it with the car on the ground. Then have a helper rock the car while you listen and feel at each component.





GETS BLAMED

Struts / Shocks
Worn struts feel bouncy, but rarely clunk.

OFTEN THE REAL CAUSE

Sway Bar End Link
Try to twist and listen/feel each component.

Sway Bar Bushing
Cracked, off-center rubber.

ALSO CHECK
Strut Mounts, Ball Joints, Control Arm Bushings, Exhaust Hangers & Heat Shields

HOW TO FIND IT

With the car on the ground, grab each sway bar end link and try to twist it. Then have a helper rock the car while you listen and feel at each component.

SUSPENSIA®

Original Equipment Fit | Direct from the Manufacturer

©2026 TrakMotive, Inc. | 1675 West Park Ave., Redlands, CA 92373 | **800.567.1608** | **info@suspensia.com** SP1-655.1

02 A Pull, Blamed on the Alignment



An alignment that checks out but still pulls is a common source of comebacks. Before you re-align, rule out these causes:



- **Radial tire pull:** if swapping the front tires left to right reverses the pull, the tire is the cause.
- **A sticking brake caliper:** after a drive, one wheel will be noticeably hotter than the other.
- **A worn lower control arm bushing:** it lets the wheel shift under braking or acceleration.
- **A binding strut mount:** it causes "memory steer," where the car pulls in the direction of the last turn.

GETS BLAMED

Alignment
Specs check out - but the car still pulls.

OFTEN THE REAL CAUSE

Radial Tire Pull
Swap fronts, if pull reverses, it's the tire.

Sticking Brake Caliper
After driving, one wheel is noticeably hotter.

Lower Control Arm
Worn bushing lets wheel shift on brake/throttle.

Binding Strut Mount
"Memory steer" pulls toward the last turn.

HOW TO FIND IT

Before you re-align, rule these out. Swap the front tires, compare wheel temperatures after a drive, and inspect the lower control arm bushings and strut mounts.

03 Loose Steering or Wander Blamed On the Steering Rack



Play at the wheel often comes from somewhere else: a ball joint, control arm bushings, or a worn wheel bearing. How you check matters. Grab the tire at 9 and 3 o'clock and rock it. Play points to tie rods or the rack. Play when you rock it at 12 and 6 points to ball joints or a wheel bearing. Have a helper watch each joint so you can see where the movement actually is. When checking ball joints, remember that a load-carrying joint has to be unloaded before its play will show. If the coil spring sits on the lower control arm, support the lower arm near the joint. On strut designs, lift by the frame. When the spring sits on the upper arm, lift by the frame and wedge a block between the upper arm and the frame. Lifting at the wrong point can hide the wear. If the joint has a wear indicator, use it.



ALSO CHECK
Control Arm Bushings

GETS BLAMED

Steering Rack
Play at the wheel often starts elsewhere.

OFTEN THE REAL CAUSE

Rock at 12 & 6 OFTEN MISSED
Play here → ball joints or a worn wheel bearing.

Rock at 9 & 3
Play here → tie rods or the steering rack.

HOW TO FIND IT

Unload a load-carrying ball joint: support the lower arm if the spring sits on it; lift by the frame on struts. Have a helper watch each joint while you rock the tire.

SUSPENSIA®

Original Equipment Fit | Direct from the Manufacturer

©2026 TrakMotive, Inc. | 1675 West Park Ave., Redlands, CA 92373 | **800.567.1608** | **info@suspensia.com** SP1-655.1

04 Tire Wear Blamed On Alignment When the Alignment Is In Spec



The printout is all green, but the tires keep wearing on the inside or feathering. Often the cause is a worn chassis part that the alignment rack can't detect.

- **Bushing deflection:** A worn control arm, trailing arm, or subframe bushing can hold correct specs on the alignment rack but still let toe shift under braking, acceleration, or cornering. The rack measures a static car, while the tire wears dynamically. Pry gently on each arm and look for rubber that is cracked, torn, or pushed off center.
- **The rear axle gets ignored:** Many shops do a front-only alignment on vehicles with adjustable or independent rear suspension. Rear toe or thrust angle that's off makes the car "dog track," the front tires wear while the driver holds a slight steering correction.
- **Other factors:** Running tires underinflated, carrying heavy loads (which changes camber and toe), skipping rotations, and worn shocks (which cause cupping) all produce wear patterns that look like an alignment problem.

GETS BLAMED

Alignment
Specs check out - but the car still pulls.

OFTEN THE REAL CAUSE



Bushing Deflection
In-spec but toe shifts when the car moves.



Rear Ignored
Off rear toe / thrust angle makes the car "dog track".



Inner-Edge Wear
or feathering, despite an all-green printout.

ALSO CHECK
Underinflation, Heavy Loads, Skipped Rotations, Worn Shocks (cupping)

HOW TO FIND IT
Pry gently on each control arm, trailing arm and subframe mount - look for rubber that is cracked, torn, or pushed off center. Check rear toe and thrust angle too.

05 Heavy Steering or Poor Return-to-Center Blamed on the Power Steering



When steering feels stiff, notchy, or doesn't straighten itself after a turn, the pump, rack, or electric assist motor usually gets replaced first. Often the real cause is binding in the steering linkage or front suspension, which the power steering system then has to fight. A tie rod end or ball joint costs a fraction of what a new rack does. Common causes:

- **Seized or dry tie rod ends and ball joints:** Joints can bind without looseness, passing play checks while causing heavy steering and poor return. Disconnect and move the stud by hand; it should move smoothly without tight spots or notches.
- **Binding upper strut mount bearings:** Cause stiff or notchy steering, often with a low-speed creak, pop, or spring "boing." Steering may not return to center after a turn.
- **Low or uneven caster:** Reduces steering return and can cause a pull toward the side with less caster. Causes include bent control arms or strut towers, shifted subframes, and worn radius rod or control arm bushings.



GETS BLAMED

Pump, Rack or Assist Motor
The system may be fighting a bind.

A tie rod end or ball joint costs a fraction of a new rack.

OFTEN THE REAL CAUSE

Seized Tie Rod End / Ball Joint
No play, but stiff to move.

Binding Strut Mount Bearing
Notchy; won't self-center.

Low or Uneven Caster
Weak return-to-center.

HOW TO FIND IT
Disconnect each joint and move the stud by hand. It should move smoothly, with no notches or tight spots - a joint can pass a play check and still bind.

SUSPENSIA®

Original Equipment Fit | Direct from the Manufacturer

©2026 TrakMotive, Inc. | 1675 West Park Ave., Redlands, CA 92373 | **800.567.1608** | **info@suspensia.com**